



AXIS COMMUNICATIONS



Assembly Instruction
AXIS T98A-VE Sunshield
© Axis Communications AB, 2012
Ver.1.0
Printed: June 2012
Part No. 47705