

M VESA Flexarm 360 I M VESA Flexarm 360 II M VESA Flexarm 360 III

- ar والبلازما TFT و LCD حامل التركيب على الجدار لشاشات
- dk Vægbeslag til LCD-skærm, TFT-skærm og plasmaskærm
- de Wandhalterung für LCD-, TFT- und Plasma-Geräte
- el Βραχίονας Τοίχου για οθόνες LCD, TFT και
- en Wall Bracket for LCD, TFT and Plasma
- es Soporte de pared para LCD, TFT y Plasma
- fi Seinäkiinnike LCD-, TFT- ja plasmanäytöille
- fr Support mural pour écrans LCD, TFT et plasma
- it Staffa per il montaggio a parete di LCD, TFT e plasma
- nl Muurbeugel voor LCD, TFT en Plasma
- no Veggbrakett for LCD, TFT og plasma
- pl Uchwył ścienny do monitora LCD, TFT i plazmowego
- ru Стенной кронштейн для ЖК, плазменного телевизора или TFT
- se Väggfäste för LCD-, TFT- och plasmaskärm
- tr LCD, TFT ve Plazma Duvar Desteği
- zh LCD, TFT 和等离子电视的壁上支架

**Warning!**

Always check the depth of the holes before starting an installation.

تحذير!

المحض دائماً عمق الثقوب قبل أن تبدأ في عملية التركيب.

ADVARSEL!

Kontroller altid hullernes dybde, før du går i gang med en installation.

WARNUNG!

Vor Beginn des Einbaus immer die Tiefe der Bohrungen überprüfen.

ΠΡΟΕΙΔΟΠΟΙΗΣΗ!

Ελέγχετε πάντοτε το βάθος των οπών προτού ξεκινήσετε την εγκατάσταση.

VAROITUS!

Always check the depth of the holes before starting an installation.

¡AVISO!

Controla siempre la profundidad de los agujeros antes de iniciar una instalación.

VAROITUS!

Selvitä reikien syvyys ennen asentamisen aloittamista.

ATTENTION !

Vérifiez toujours la profondeur des trous avant de commencer l'installation.

ATTENZIONE!

Verificare sempre la profondità dei fori prima dell'installazione.

ADVARSEL!

Sjekk alltid hvor dype hullene er før du begynner å montere.

OSTRZEŻENIE!

Przed przystąpieniem do montażu należy koniecznie sprawdzić głębokość otworów.

ПРЕДУПРЕЖДЕНИЕ!

Перед установкой всегда проверяйте глубину отверстий.

VARNING!


Kontrollera alltid hålets djup innan en installation påbörjas.

UYARI!

Montaja başlamadan önce daima deliklerin derinliğini kontrol edin.


警告!

请始终在安装前检查孔洞的深度。




																		x1			x1			x1			x8			x8			x4		
																M	4mm		N	5mm		O	6mm		P	M5X14		Q	M5		R				
		x4			x8			x4			x4			x4			x4			x4			x4			x4			x3			x3			x1
A	M4x14		B	M5X14		C	M5x14		D	M6x14		E	M8x16		F	D4		G	D5		H	D6		I	#1.5x5.5x3.2		J	Ø8x36		K	M5.5x50		L	3mm	


2



Flexarm 360 I




Flexarm 360 II




Flexarm 360 III


3



a





b





c


4




5



6





Backside





Frontside



a







b




c



7



8



Stop 360 rotation possibility

