


## USB-C/USB-A 2-in-1 M.2 NVMe Dock Adapter - 10Gbps

### Product ID

1USB3-NVME-DOCK



| Component |                               | Function                                                                                                                                                                                   |
|-----------|-------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1         | M.2 NVMe Drive Slot           | <ul style="list-style-type: none"> <li>Insert an <b>M.2 NVMe Drive</b></li> <li>Toaster-style design for heat dissipation</li> </ul>                                                       |
| 2         | LED Indicator                 | <ul style="list-style-type: none"> <li><b>Solid:</b> Drive detected</li> <li><b>Flashing:</b> Read/Write activity</li> </ul>                                                               |
| 3         | USB-C Host Connector - 10Gbps | <ul style="list-style-type: none"> <li>Connect to a <b>USB-C Port</b> on a <b>Host Computer</b></li> <li>Detach the <b>USB-A Adapter</b> from the integrated <b>USB-C Cable</b></li> </ul> |
| 4         | USB-A Adapter - 10Gbps        | <ul style="list-style-type: none"> <li>Connect to a <b>USB-A Port</b> on a <b>Host Computer</b></li> <li>Attaches onto the integrated <b>USB-C Cable</b></li> </ul>                        |

### Requirements

- M.2 NVMe Drive
- Computer with an available USB-C or USB-A port

### Package Contents

- USB-C/USB-A 2-in-1 M.2 NVMe Dock Adapter x 1
- Quick-Start Guide x 1

For the latest product information, technical specifications, and declarations of conformance, please visit:

[www.StarTech.com/1USB3-NVME-DOCK](http://www.StarTech.com/1USB3-NVME-DOCK)

### Operation

**Warning!** M.2 Drives can become hot during prolonged data transfer sessions. Avoid touching the M.2 Drive immediately after use to prevent possible burns. Allow the drive to cool down before removing/handling.

**Warning!** Always eject the drive safely through the Operating System before disconnecting. Avoid hot-swapping drives to prevent data loss or device damage.

1. Insert the **M.2 NVMe Drive** vertically into the **USB-C/USB-A 2-in-1 M.2 NVMe Dock Adapter**.
2. Connect the **USB-C/USB-A 2-in-1 M.2 NVMe Dock Adapter** to an available **USB-C** or **USB-A Port** on the **Host Computer**.
  - If your computer has only USB-A ports, attach the included **USB-C to USB-A Adapter** on the integrated USB-C Cable on the **USB-C/USB-A 2-in-1 M.2 NVMe Dock Adapter**.



**HQ Contact:**  
StarTech.com Ltd.  
45 Artisans Crescent,  
London, ON N5V 5E9,  
Canada

**US Contact:**  
StarTech.com USA LLP  
4490 South Hamilton Rd,  
Groveport, OH 43125,  
United States

**UK Contact:**  
StarTech.com Ltd.  
15 Gowerton Rd,  
Northampton, NN4 7BW,  
United Kingdom

**EU Contact:**  
StarTech.com Ltd.  
Siriusdreef 17-27  
2132 WT Hoofddorp  
The Netherlands

**JP Contact:**  
StarTech.com K.K.  
Atelier Yours Ogawamachi 7F  
1-10-2 Kanda Ogawamachi  
Chiyoda-ku, Tokyo 101-0052  
Japan

FR: startech.com/fr  
DE: startech.com/de  
ES: startech.com/es  
NL: startech.com/nl  
IT: startech.com/it

For additional self-service support options and community forums, please visit: [www.StarTech.com/support](http://www.StarTech.com/support)

Revision: November 3, 2025